

CONTRACTOR'S EQUIPMENT

FIRE

The insured was using an excavator to clear land for a new subdivision. The excavator caught on fire. The fire started from wires around the battery making contact with combustible materials.

THEFT

A local golf course had a brush chipper that was used to clear tree limbs and brush from the course. The brush chipper was stored outside in a locked fenced area. During the night someone drove their vehicle onto the grounds, cut the lock on the fence, and drove off with the brush chipper. The equipment was never recovered.

MECHANICAL BREAKDOWN

The insured was using an excavator to lift a steel beam. The weight was too much for the arm and caused it to bend resulting in a complete replacement of the arm.

VANDALISM

Equipment was at a job site that was surrounded by woods and a wooden fence. Vandals came in the night and set fire to the unit causing a total loss.

AGOSTINI
WHOLESALE
INSURANCE

(800) 922-7283 WWW.AGOSTINISURPLUS.COM

For an application and more information, please visit AgostiniSurplus.com

Teresa Tallarida, Commercial Underwriter

Phone (619) 593-2045 • Fax (619) 593-2075 • E-mail teresa@agostinisurplus.com

This document does not amend, extend or alter the coverage afforded by the Policy. For a complete understanding of any insurance you purchase, you must first read your Policy, Declaration Page and any Endorsements and discuss them with your Broker. A specimen policy is available from an Agent of the Company. Your actual Policy Conditions may be amended by Endorsement or affected by State Laws.

SRN120909C